$\mbox{CO}_2\/\mbox{Temp}\/\/\mbox{RH}$ Indoor Air Quality Meter

Users Manual V.1.0

TABLE OF CONTENTS

1.	FEATURES & SPECIFICATIONS	3
2.	WHAT'S IN THE BOX	6
3.	START UP AND GENERAL OPERATION	7
	Start Up	7
	LCD Display	8
	Display Screen (1-7)	9
	Clear Memory	9
	Recording and Datalogging	10
	Datalogging Power Saving Mode	11
	CFM / P (Cubic Foot Per Minute per Person) Calculation Example	12
	Parameter Setup Screen (1-5)	13
	0ppm and 400ppm CO2 Calibration	19
4.	PC SOFTWARE & DRIVER INSTALLATION	21
5.	USING PC SOFTWARE	25
6.	WARRANTY	33

1. FEATURES & SPECIFICATIONS

Features

- 3 Independent CO₂, humidity and temperature sensors.
- User operated CO₂ calibration.
- Datalogging : 50,000 records.
- Fast USB download (50,000 records in less than 10 seconds).
- Internal backup battery to maintain date / time setting.
- Power management IC to increase batter efficiency.
- Easy- to-Use PC software for parameter settings and data analysis.
- Internal CO₂ alarm buzzer.

Specifications

- CO₂ Sensing Method : NDIR (Non-Dispersive Infrared)
- Measures : Carbon dioxide in PPM, temperature (°F or °C), % Relative Humidity
- CO₂ Measurement range : 0~9999 ppm (2001~9999 ppm over range)
- CO₂ Accuracy : ± 75ppm, ± 8% of reading (0~2000 ppm)
- Display Resolution : ±1 ppm
- Datalogging : 50,000 records.

Applications

- Building HVAC monitoring.
- Indoor air quality survey.
- Locate the presence of combustion fumes from vehicles and

appliances.

General

Operation Condition	32-122 [°] F (0-50 °C)	
	0-95%,RH,non-condensing	
Storage Temperature	-4 to 140 [°] F (-20 to 60 [°] C)	

CO₂ Sensor

Туре	Non-dispersive infra-red (NDIR)
Measurement Range	0~9999 ppm (2001~9999 ppm over range)
Accuracy	± 75ppm, ± 8% of reading (0~2000 ppm)
Resolution	±1 ppm
Response Time	Reaches 90% in approximately 2 minutes

Relative Humidity Sensor

Туре	CMOSens	
Measurement Range	1%-99%	
Accuracy	±3.0%RH(20~80%) at 25°C	
	±5.0%RH(<20%,>80%) at 25°C	
Resolution	0.1%	
Response Time	8 Seconds	

Temperature Sensor

Туре	Thermistor
Measurement Range	0 to 50 [°] C
Accuracy	±1.0 [°] C from 0-50 [°] C
Resolution	0.1 [°] C
Response Time	1 seconds

Power Supply

Battery	4 AA alkaline battery
Battery Operation	24 hours
External Power Supply	6V VDC with 0.5A

2. WHAT'S IN THE BOX



3. START UP AND GENERAL OPERATION

Start Up

• Hold the 0 Power button for 2 seconds to turn on Meter.



- Wait few seconds until the "Warm-up" sign turns off.
- The unit is ready to use.

LCD Display



1.	Warm Up	12.	Meter / Foot
2.	Recording	13.	% PPM
3.	Calibration	14.	Temperature Reading
4.	USB	15.	Flow Rate
5.	Outside- CO2	16.	Time & Date
6.	Setting	17.	Elevation
7.	Alarm	18.	Humidity
8.	High	19.	Memory Left
9.	Low	20.	Battery
10.	Maximum	21.	CO2 Reading
11,	Minimum		

1.	Mode	Mode	4.		Down Arrow
2.	Enter	Enter	5.		Up Arrow
3.	0	Power	6.	Rec	Record

Meter Buttons

Display Screen (1-7)

1. 2.		3.	4.	
CO2 F Humidity Temperature 80.0 % 80.0 °F 08:08~ 12/30/08	CO2 F Humidity BOOD % RH BOOD °C D8:08% 12/30/08	CO2	Max CO2 Humidity Humidity BOLO % BOLO % BOLO % Competence F BOLO % BOLO % BOLO % Competence F BOLO % Competence F Competence Competence F Competence Competence F Competence Competence Competence Competence Competence Competence Competence Competence Competence Competence Competence	
			Maximum	
Main Screen	Main Screen	% of Memory Left	Reading:	
			CO₂ / Rh / Temp	

5.	6.	7.	
Min CO2 F Humidity Temperature BOLO [*] / [*] / [*] 08:08-~ 12/30/08	CO ₂	CO ₂	
Minimum Reading:			
<u> </u>	CFM / P ventilation	l / n / s Ventilation	
	(Cubic Foot Per		
Humidity &		(Liter Per Second)	
Temperature	Minute Per Person)		

- Press **V** to rotate the screen in the clockwise direction.=2
- Press (to rote the screen in the counter-clockwise direction.

Clear Memory

• Press enter & together to clear the datalogging memory and restore the memory capacity back to 100%.

Recording and Datalogging

Hold **Rec** for 2 seconds to start data recording.



Sampling rate (5sec / 10sec / 1min / 5min / 10min / 30min / 1 hour / 2 hour)

can only be set from PC setup screen.

🗖 Data Logger Setup					×
Setting GENERAL Product# Current Date&Time Start Date&Time End Date&Time Unit Description Interval	PPM PPM %RH %RH F F	I Time sync Temperature I IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	hronization e Unit C C		
Outside CO2	PPM				
		<u> </u>		Save Settings	Close

Datalogging Power Saving Mode

Sampling rate longer than 5 minutes (5min / 10min / 30min / 1 hour) will automatically turn on power-saving mode. The Meter will be in power-saving mode during the non-sampling period. One minute before the sampling time, the Meter will turn on to take the sample. After the sampling is done, the Meter will turn back to power-saving mode. While in the power-saving mode, the Meter will not respond to any key inputs.

Hold **Rec** for 2 seconds to exit the datalogging mode.

Sampling Interval	Power-Saving
5 seconds	
10 seconds	
1 minutes	
5 minutes	\checkmark
10 minutes	\checkmark
30 minutes	\checkmark
1 hour	\checkmark
2 hour	\checkmark

CFM / P (Cubic Foot Per Minute per Person) Calculation Example

CFM/P=10600 / (Cs-Co)

- Cs=CO2 reading
- Co=CO2 outside reading

Example:

10,600 Constant

- 650 Cs=CO₂ reading
- 400 Co=CO₂ outside reading
- 42.4 CFM / P
- 10,600 / (650-400) = 42.4 (CFM / P)

L / P / S (Liter Per Second)

L / P / S= (CFM/P)x28.32 / 60

Example:

48.60	=CFM / P (Cubic Foot Per Minute / person)
28.32	=1 Cubic Foot = 28.3168466 Liters
60.00	=Divided by 60 to get per second reading
22.9	=L / P / S (Liter Per Second)

48.6 x28.32 / 60=22.9 (L / P / S)

Parameter Setup Screen (1-5)

1.	2.	3.	4.
Outside CO2	Setting 08:08-11 12/30/08	Setting Alarm	Setting Alarm High CO ₂
Setting Outside	Clock	Alarm Buzzer	High CO₂
CO₂ Value	Setting	Setting	Alarm Setting



1. Enter Outside CO2 Value (default setting is 400ppm)



Enter

Enter Outside CO₂ Manually:

- Press Mode + Enter to enter the setting menu.
- Press 🖤 5 times.
- Press Enter to enter the Outside CO₂ setting Menu (First digit starts to flash).
- Press Mode to rotate between digits.
- Press Enter to save.
- Press Mode and Enter to return to the Main menu.

Unit	Enter Value
1st digit	Use (Interpretending and Interpretending Select (0-9)
2nd digit	Use 🔺 and 💌 Select (0-9)
3rd digit	Use 🚺 and 💌 Select (0-9)
4th digit	Use (Interpretendent of the Use (0-9)

2. Clock Setting



- Press to save and exit the Time Setting menu.
- Press Mode and Enter to return to the Main menu.

Unit	Enter Value (0-9)	Range
Hour	Use 🚺 and 🔽	(0AM -11PM)
Minute	Use 🔺 and 🔽	(0-59)
Month	Use 🔺 and 🔍	(1-12)
Date	Use 🔺 and 🔍	(1 to 31)
Year	Use 🚺 and 🔽	(2001-2037)

3. Audible Alarm Setting



- Mode and Enter to enter the setting menu. Press
- Press **V** 2 times.
- to enter the Audible Alarm Setting Page. Current audible Press alarm status (On / Off) will start to flash.
- And v keys to switch between On / Off. Use
- Enter to save and exit. Press
- and Enter to return to the Main menu. Press Mode

4. CO2 High Alarm Setting



- Press Mode and Enter to enter the setting menu.
- Press 🖤 3 times.
- Press Enter to enter the High Alarm Setting Menu (First digit starts to flash).
- Press ^{Mode} to rotate between digits.
- Press to save and exit the High Alarm Setting menu.
- Press Mode and Enter to return to the Main menu.

Unit	Select Digit	Enter Value
1st digit	Mode	Use (A) and (V) Select (0-9)
2nd digit	Mode	Use 🔺 and 💌 Select (0-9)
3rd digit	Mode	Use 🚺 and 🔽 Select (0-9)
4th digit	Mode	Use 🔺 and 💌 Select (0-9)

5. CO₂ Low Alarm Setting



- Press Enter to enter the Low Alarm Setting Menu (First digit starts to flash).
- Press Mode to rotate between digits.
- Press Enter to save and exit the Low Alarm Setting menu.
- Press Mode and Enter to return to the Main menu.

Unit	Enter Value		
1st digit	Use 🚺 and 🔽 Select (0-9)		
2nd digit	Use 🔺 and 💌 Select (0-9)		
3rd digit	Use 🔺 and 💌 Select (0-9)		
4th digit	Use 🚺 and 💌 Select (0-9)		

<u>Oppm and 400ppm CO₂ Calibration</u>

- Press $^{\textcircled{0}}$ + $^{\textcircled{Mode}}$ together to enter CO₂ Calibration menu.
- Press ^{Enter} to start calibration.

While calibrating, the LCD will show :

Do not press any button during the calibration.



If the calibration is successful, the LCD will show :



If the calibration failed, the LCD will show:



• Press power to power off and restart again.

Now the Meter is working with new calibrated value.

4. PC SOFTWARE & DRIVER INSTALLATION

Installation Requirements:

Minimum system requirements for the software:

-Pentium III - 500 MHz processor or equivalent with 128 megabytes of RAM.

Optimal Performance:

-Pentium 4 - 2.8 gigahertz processor or equivalent with 256 megabytes or RAM.

Operating System Requirements:

-Windows 2000

-Windows XP

-Window 7

PC DRIVER INSTALLATION

• Insert the CD into the disk drive.



• Click Setup to start installation.



• Follow the steps on the Installation Shield Wizard and click Finish to complete the installation.



• Connect Meter and PC together with a USB cable.



5. USING PC SOFTWARE

- Start Window XP software.
- Click on All programs, Click on Meter.
- Click on ST Logger to start the PC program.



Connection Status

nologies, Inc.	
Setup 8	CD2 Calibration
Dow	Noad Records
Graphic & Chart	Analysis for Saved Data
Humidity:	C02:
	nologies, Inc. Setup 8 Down Graphic & Chart Humidity:

No Connection Screen



Connected Screen

Setup Screen

🖾 Data Logger Setup	
Setting CO2 Calibration GENERAL	
Product# ST501DU - USB Current Date&Time 11/17/2007 10:59:57 Start Date&Time 07/25/2007 23:28:21 End Date&Time 07/26/2007 05:01:41 Unit Description ST501DU Interval 5sec	 ✓ Time synchronization Temperature Unit C F C Ventiliation Unit C
ALARM LIMITHigh CO2 Limit100 PPMLow CO2 Limit20 PPMHigh Rh Limit90 %RHLow Rh Limit20 %RHHigh Temp Limit70 CLow Temp Limit20 C	
	Elevation Unit C Feet(ft)
	ve Settings <u>C</u> lose

• The values in the white area can be changed by the user.

High CO2 Limit 100 PPM

• The value in the inverted area can not be changed by the user.

Product# ST501DU - USB

• Click Save Settings to save the values to Meter.

Download Records

• Click Download to download the stored data.

🖾 ST501DU - Da	ta Download	×
	The records in Data Logger will be downloaded. To keep these records for purpose later, save them on disk.	
	Processing schedule: 100%	
Detailed Informati	ions	7
\ST501DU_A _47.dat succe Total file numt Download fini:	PP\STLogger\data\2007_11_17_19_05_472007_11_17_19_06 ess! ber: 1 sh!	
Help	Download Clear Logger Close	

Download completed screen

Graphic & Chart Analysis

300

250

200

150

100

50

C:\Program Files\ST501DU\data\ST501DU-some zeros.dat



100

95

90

85

80

75

70

65

40

-35

-30

-25

-20

15 10

CO2 Low Alarm

— · — · — · — · — Temp Low Alarm — · — · — · — · — Humi Low Alarm

Temperature('C) / Humidity(%)

Downloaded data will first be displayed in graphic format. •

Each data groups are listed according to the date of acquisition. Lowest •

12:11:43PM 12:22:03PM 12:33:13PM 12:44:23PM 12:55:38PM 01:06:48PM 01:17:58PM 01:29:13PM 01:40:23PM 01:51:33PM 02:02:48PM 02:13:58PM 02:25:13PM 02:26:23PM 02:06/2009 02/06/2009

From: 12:11:43PM,02/06/2009 To: 02:39:08PM,02/06/2009

----- Temp High Alarm Humi High Alarm

CO2 High Alarm

group number represents earliest acquisition date.

CO2

Temperature Humidity

File	View Export H	elp		
Ê	Q Q 10 6	🗐 🗋	°C °F	[3] 12:11:43PM,02/06/2009 -> 02:39:08PM,02/06/2009, 1770 Records
	900			[1] 12:11:10PM,02/06/2009 -> 12:11:18PM,02/06/2009, 2 Records [2] 12:11:23PM,02/06/2009 -> 12:11:33PM,02/06/2009, 3 Records [3] 12:11:43PM,02/06/2009 -> 02:39:08PM,02/06/2009, 1770 Records [4] 05:14:19PM,02/06/2009 -> 02:03:23PM,02/20/2009, 2 Records [5] 02:03:28PM,02/20/2009 -> 08:43:03PM,02/21/2009, 22076 Records [6] 09:34:07AM,08/08/2008 -> 11:16:02AM,08/08/2008, 1224 Records

Data in Text Format

To display data in Listing format:

- Click File
- Click Chart Preview



Text Listing Format

Product Name: ST501DU Description: STLogger Record Data Start Date&Time: 12:11:43PM,02/06/2009 End Date&Time: 02:39:08PM,02/06/2009 Interval: 5 seconds Record Count: 1770 CO2 Alarm High: 800 PPM CO2 Alarm Low: 300 PPM Temp Alarm Low: 300 PPM Temp Alarm Low: 32.0 'C Humi Alarm High: 90 % Humi Alarm Low: 20 %

No.	Date	Time	Temp('C)	Alarm	Humi(%)	Alarm	CO2(PPM)	Alarm
1	12:11:43PM	02/06/2009	22.7	Low	45.6		412	
2	12:11:48PM	02/06/2009	22.5	Low	45.9		415	
3	12:11:53PM	02/06/2009	22.1	Low	47.6		416	
4	12:11:58PM	02/06/2009	21.5	Low	50.0		417	
5	12:12:03PM	02/06/2009	20.8	Low	52.5		411	
6	12:12:08PM	02/06/2009	20.6	Low	54.3		410	
7	12:12:13PM	02/06/2009	20.8	Low	55.4		409	
8	12:12:18PM	02/06/2009	20.8	Low	57.3		406	
9	12:12:23PM	02/06/2009	20.7	Low	58.4		404	
10	12:12:28PM	02/06/2009	20.9	Low	59.8		401	
11	12:12:33PM	02/06/2009	20.6	Low	60.4		396	
12	12:12:38PM	02/06/2009	20.5	Low	60.9		393	
13	12:12:43PM	02/06/2009	20.6	LOW	61.2		388	
14	12:12:48PM	02/06/2009	20.6	Low	61.2		384	
15	12:12:53PM	02/06/2009	20.6	Low	61.2		378	
16	12:12:58PM	02/06/2009	20.7	Low	61.2		372	
17	12:13:03PM	02/06/2009	20.8	Low	61.3		367	
18	12:13:08PM	02/06/2009	20.5	Low	61.7		363	
19	12:13:13PM	02/06/2009	20.5	Low	62.2		358	
20	12:13:18PM	02/06/2009	20.6	LOW	62.4		355	
21	12:13:23PM	02/06/2009	20.3	Low	62.4		352	
22	12:13:28PM	02/06/2009	20.3	Low	62.5		350	
23	12:13:33PM	02/06/2009	20.0	Low	63.2		346	
24	12:13:38PM	02/06/2009	19.9	LOW	64.0		344	
25	12:13:43PM	02/06/2009	20.0	Low	64.3		339	
26	12:13:48PM	02/06/2009	20.1	Low	64.1		337	
27	12:13:53PM	02/06/2009	20.2	Low	63.7		334	
28	12:13:58PM	02/06/2009	20.0	Low	63.8		333	
29	12:14:03PM	02/06/2009	19.9	Low	64.1		329	
30	12:14:08PM	02/06/2009	19.8	Low	64.4		326	
31	12:14:13PM	02/06/2009	19.8	Low	64.5		325	
32	12:14:18PM	02/06/2009	19.7	Low	64.8		324	
33	12:14:23PM	02/06/2009	19.6	Low	65.6		323	
34	12:14:28PM	02/06/2009	19.6	LOW	65.9		322	
35	12:14:33PM	02/06/2009	19.8	Low	65.7		321	
36	12:14:38PM	02/06/2009	19.8	Low	66.0		319	
37	12:14:43PM	02/06/2009	19.8	Low	66.1		318	
38	12:14:48PM	02/06/2009	19.9	Low	66.0		316	
39	12:14:53PM	02/06/2009	19.9	Low	65.8		316	
40	12:14:58PM	02/06/2009	19.8	Low	65.6		315	
41	12:15:03PM	02/06/2009	19.8	Low	65.3		314	
42	12:15:08PM	02/06/2009	19.9	LOW	64.8		313	

Printed 3/4/2009

Page 1

Data Export

Select export data type: Text or Excel CSV



Save in:	My Documents		- 🗧 📥 📰	•
	Adobe		C ST501_20090717	
	Download		C ST501_20090720	
My Recent Firefox Saved File			C 5T501_20090722	
			jon vb	
	My Music		🐴 2.17.09	
	🛅 My PaperPort Docur	nents	4.2.08	
Desktop	💾 My Pictures		🐴 7.19.09	
	🕮 My Videos		A 12.11.08	
	Paperport Print		E]55	
	Print Here		E 63	
4y Documents	🚞 RealPlayer Downloa	ds	99	
	adk		SIRIUS_TECHNOLOG	IES_INC_MARC
	Creen2exe 2.1		🐴 st501 battery voltage	e test
	🛅 Sirius		🐴 tess	
	ST300_Setup		🖳 tesst	
	<			C
My Network	File name: 🛛 🔯	ado	_	Save
Places				0.1

Click Save to save the file in .CSV/Txt format.



File Saved.

6. <u>WARRANTY</u>

Meter is warranted for a period of twelve (12) months from the date of purchase to be free of defects in material or workmanship. This warranty does not apply to damage resulting from accident, alteration, abuse, loss of parts or repair by other than Sirius Technologies, Inc. The equipment will be repaired or replaced, at our option, without charge to the owner for parts or labor incurred in such repair. This warranty shall not apply unless the equipment is returned for our examination with all transportation charges prepaid.