- # **ST9620 Lux meter**

Product No.: ST9620

FEATURES:

1. Measure the Luminosity of any light source.
2. Conversion of Luminosity units.
3. Data Hold with Maximum and Minimum.
4. Low power indication.
5. Auto or manual power off function.
6. Temperature measurement function.
7. Unit with high and low Luminosity alarm function.

SPECIFICATIONS

Measuring Range	1~200.000lux
Accuracy	±3%
Unit Selection	lux / FC
Response time	1.5s
Sampling Frequency	2 time/sec
Resolution	1lux
Data Hold Function	√
Backlight Display	√
Measuring Level selection	Automatism Max/Min reading
REC Test	√
Over Level indication	√
Colour Display	√
High & low Luminosity Alarm Function	√
Power	3*1.5V AAA Battery